#### NARRATIVE REPORT

#### 1.0 **BUILDING INFORMATION**

Northern Crops Institute was originally constructed in 1983; the building has had no major renovations.

Northern Crops Institute is a three-story, 25,143 ft<sup>2</sup> building which primarily serves as office areas and work areas for agricultural personnel. Harris Hall (A028) is attached to the north side of the Northern Crops Institute and is reported separately. The Durum Mill, a 1990 addition to the Northern Crops Institute and Harris Hall, is reported with Harris Hall (A028).

The interior floor finishes included floor tile, carpet, and concrete; the interior wall finishes included gypsum wallboard, concrete block, and brick; and the interior ceiling finishes included ceiling tile, gypsum wallboard, metal, and concrete. The roofing system is a flat rubbermembrane roof and the exterior of the structure is brick.

The piping systems were insulated; fiberglass insulation (without hard fittings) is located throughout the building. Steam enters the building from Harris Hall (A028) and domestic water enters the building in room 42. HVAC systems located in the building consisted of forced air furnaces with variable air volume boxes equipped with heating/cooling coils throughout the building.

#### 2.0 **ASBESTOS SURVEY INFORMATION**

Northern Crops Institute was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 9" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 9" for methodologies, definitions, and other pertinent supporting information.

A total of 39 samples were collected from suspect asbestos-containing materials (ACM) from the Northern Crops Institute on May 14, 2007, 3 additional samples were collected on November 20, 2007, and 1 additional sample was collected on November 29, 2007. Laboratory analysis results indicate 6 of these samples tested positive for asbestos.

#### 2.1 **Suspect Materials Identified and Sampled**

Encapsulant on Fiberglass Insulation Ceiling Tile (2 types)

Carpet Mastic

**HVAC Duct Caulk** 

Floor Tile

Spray-on Fireproofing

Joint Compound

**Exterior Window Caulk** 

Transite Fume Hood

Sink Undercoating **Baseboard Adhesive** Black Layer (on fiberglass)

Door Caulk Floor Tile Mastic **Gypsum Wallboard** 

Exterior Window Glazing (2 types)

Sink/Counter Undercoating

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

### 2.2 <u>Asbestos Containing Materials</u>

White Sink Undercoating Exterior Window Glazing (around main entry) Mastic for 12" White Floor Tile w/ Brown Marks Black Sink/Counter Undercoating Transite Fume Hood

The ACM Locations/ Friable Materials Assessments Table includes ACM locations data.

### 2.3 **Cost Estimates**

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for Northern Crops Institute as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Floor Tile Mastic	3,132 ft <sup>2</sup>	\$4.00/ft <sup>2</sup>	\$12,528.00
Asbestos Window Glazing	36 ea	\$225.00/ea	\$8,100.00
Asbestos Sink Undercoating	6 ea	\$150.00/ea	\$900.00
Asbestos Sink/Counter Undercoating	1 ea	\$350.00/ea	\$350.00
Asbestos Transite Fume Hood	1 ea	\$350.00/ea	\$350.00
Total Estimated Abater	\$22,228.00		

# LEGEND TECHNICAL SERVICES, INC.

## ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

## LEGEND No. 0700048 (NDSU) NORTHERN CROPS INSTITUTE (BUILDING A093)

-	1	1			,		
ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE 5 € E E POTENTIAL	ASSESS. CAT. <sup>1</sup>	NOTES
		1				•	
Room 41B							
Mastic for 12" White	15% Chrysotile	120 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown			Miscellaneous				asbestos.
Marks							
	I	II.		•		·I	,
Room 42							
Mastic for 12" White	15% Chrysotile	24 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown			Miscellaneous				asbestos.
Marks							
		1	I.	I.		1	
Room 43							
Mastic for 12" White	15% Chrysotile	27 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown	,		Miscellaneous		,	,	asbestos.
Marks							
Room 44							
Mastic for 12" White	15% Chrysotile	55 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown	2575 5 ,5555		Miscellaneous	.,,,,	,	,	asbestos.
Marks							
						1	
Room 47							
Mastic for 12" White	15% Chrysotile	72 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown	== 70 0 1000		Miscellaneous		,,,	,	asbestos.
Marks							
Room 141							
Mastic for 12" White	15% Chrysotile	65 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown	, , , , , , , , , , , , , , , , , , ,		Miscellaneous		,	,	asbestos.
Marks							

# LEGEND TECHNICAL SERVICES, INC.

## ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

## LEGEND No. 0700048 (NDSU) NORTHERN CROPS INSTITUTE (BUILDING A093)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE 5 5 5 F F F F F F F F F F F F F F F F	ASSESS.	NOTES
			1		<u> </u>		<u> </u>
Room 142	1		1			1	
Mastic for 12" White	15% Chrysotile	35 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown Marks			Miscellaneous				asbestos.
					2.424		
White Sink Undercoating	15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	There is one sink in the room, it is along the west wall.
Room 143A						-1	
Mastic for 12" White	15% Chrysotile	145 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown Marks	,		Miscellaneous		,		asbestos.
TTTGTTG							
Room 144							
White Sink	15% Chrysotile	1 ea	Non-Friable	N/A*	N/A*	N/A*	The sink is in the northeast corner.
<del>Undercoating</del>	,		Miscellaneous				
Room 144A							<u> </u>
White Sink	15% Chrysotile	1 ea	Non-Friable	N/A*	N/A*	N/A*	The sink is along the middle of the south wall.
Undercoating	1370 CHI YSOCHE	1 64	Miscellaneous	N/A	N/A	19/7	The sink is along the initiale of the south wall.
Hallway 188							<u>I</u>
Mastic for 12" White	15% Chrysotile	716 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown Marks			Miscellaneous	,	.,,		asbestos.
And 29	9LAbated July	2024	1		<u> </u>		1
KOOM 241			1				1
Mastic for 12" White	15% Chrysotile	1,189 ft <sup>2</sup>	Non-Friable	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain
Floor Tile w/ Brown Marks			Miscellaneous				asbestos.
			1	1	ı		Dage 2 of 2

<sup>\* =</sup> Non-Friable materials were not assessed

## LEGEND TECHNICAL SERVICES, INC.

### ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
NORTHERN CROPS INSTITUTE (BUILDING A093)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE 5 € 5 E POTENTIAL	ASSESS. CAT. <sup>1</sup>	NOTES
Room 242							
White Sink Undercoating	15% Chrysotile	3 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The three sinks are in the counter systems in the middle of the room
Transite Fume Hood	15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The transite fume hood is in the northwest corner of the room.
Room 243							
Black Sink/Counter Undercoating	5% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The sink is in the southwest corner of the room. The undercoating is on the sink and the counter. Approx: 2'x9'
Room 288		·					
Mastic for 12" White Floor Tile w/ Brown Marks	15% Chrysotile	684 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	Mastic only, the floor tile does not contain asbestos.
299L see 241-Ab	ated July 2024				1		
Exterior							
Window Glazing	15% Chrysotile	36 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos window glazing is on the windows surrounding the main entrance on the east side of the building.

<sup>&</sup>lt;sup>1</sup>Assessment Categories:

- 1) Damaged or Significantly Damaged TSI ACM
- 2) Damaged Friable Surfacing ACM
- 3) Significantly Damaged Friable Surfacing ACM
- 4) Damaged or Significantly Damaged Friable Miscellaneous ACM

- 5) ACM with Potential for Damage
- 6) ACM with Potential for Significant Damage
- 7) Any Remaining Friable ACM or Friable Suspected ACM

#### End

<sup>\* =</sup> Non-Friable materials were not assessed