

NARRATIVE REPORT

1.0 BUILDING INFORMATION

Seim Hall was originally constructed in 1972; although specific information could not be located, small renovations, primarily on the 1st floor, are evident.

Seim Hall is a ten-story, 64,696 ft² building which primarily serves as dormitory areas for students. Pavak Hall (A077) and the West Dining Center (A080) are attached via a tunnel system to the south side of Seim Hall and are reported separately; the tunnel is reported with West Dining Center (A080).

The interior floor finishes included concrete, floor tile, carpet, and ceramic tile; the interior wall finishes included concrete block, concrete, gypsum wallboard, plaster, ceramic tile, and wood; and the interior ceiling finishes included concrete, ceiling tile, gypsum wallboard, plaster, ceramic tile, and metal. The roofing system is a flat built-up roof and the exterior of the structure is brick.

The piping systems were insulated; fiberglass pipe insulation (with and without hard fittings) is located throughout the building and mag block pipe insulation (with hard fittings) is located throughout room 1. Steam and domestic water enter the building in room 4. The building supplies heating/cooling lines to West Dining Center (A080). HVAC systems located in the building consisted of steam radiators and forced air furnaces equipped with heating/cooling coils.

2.0 ASBESTOS SURVEY INFORMATION

Seim Hall was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 8" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 8" for methodologies, definitions, and other pertinent supporting information.

LEGEND was granted full access to Seim Hall during the initial walk-through and sampling of the building. During subsequent walk-throughs of the building, for resampling and reporting purposes, LEGEND was granted access to the common areas and to 2-4 dormitory rooms per floor, only. For the remainder of the dormitory rooms, LEGEND identified the locations of ACMs using survey notes taken during the initial walk-through of the building.

A total of 103 samples were collected from suspect asbestos-containing materials (ACM) from Seim Hall on May 31, 2007, an additional 14 samples were collected on February 21, 2008, an additional 3 samples were collected on February 27, 2008, and an additional 1 sample was collected on March 19, 2008. Laboratory analysis results indicate **50 of these samples tested positive for asbestos.**

2.1 Suspect Materials Identified and Sampled

Floor Tile (4 types)
Ceiling Tile (5 types)
Wood Panel Adhesive
Baseboard Adhesive (3 types)
Gypsum Wallboard

Floor Tile Mastic (4 types)
Soffit Surfacing (concrete)
Carpet mastic (3 types)
Wall Texture (2 types)
Joint Compound (5 types)

Sink Undercoating (2 types)
 Hard Plaster- Skimcoat
 HVAC Canvas Connector
 Mag Block Pipe Insulation
 Window Glazing
 Rainleader Bowl Insulation
 Sprayed-On Fireproofing
 Exterior Building Seam Caulk
 Exterior Incinerator Exhaust Coating
 Exterior Penetration Putty (3 types)
 Penetration Concrete (around incinerator exhaust)

Ceiling Texture (5 types)
 Hard Plaster- Basecoat
 Tank Insulation (4 types)
 Hard Fittings on Fiberglass Insulation
 HVAC Duct Caulk
 Troweled-On Fireproofing (3 types)
 Exterior Window Caulk
 Exterior Surfacing (on concrete)
 Exterior Air Vent Caulk (on roof)
 Roof Flashing

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

2.2 **Asbestos Containing Materials**

12" Tan Floor Tile with Brown Streaks and Mastic
 Mastic for 12" Beige Floor Tile
 Wood Panel Adhesive
 Joint Compound (2 types)
 Pink Sink Undercoating (2 types)
 Light Ceiling Texture
 Heavy Ceiling Texture
 Lobby Ceiling Texture
 Heavy Wall Texture
 Dorm Room Ceiling Texture
 Tank #76-003-22 Insulation
 Tank #76-003-15 Insulation
 Tank # 76-003-08 Insulation
 Tank #76-003-23 Insulation
 Mag Block Pipe Insulation
 Orange HVAC Duct Caulk
 Window Glazing
 Exterior Air Vent Caulk (on roof)
 Exterior Penetration Putty (on cables) (on roof)
 Roof Flashing
 Hard Fittings on Mag Block Insulation (assumed)

The ACM Locations/ Friable Materials Assessments Table includes ACM locations data.

2.3 **Cost Estimates**

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for Seim Hall as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Floor Tile and/or Mastic	34,378 ft ²	\$4.00/ft ²	\$137,512.00
Asbestos Ceiling Texture (all types)	35,927 ft ²	\$7.50ft ²	\$269,425.50
Asbestos Wall Texture	1,290 ft ²	\$7.50/ft ²	\$9,675.00

Asbestos Sink Undercoating	2 ea	\$150.00/ea	\$300.00
Asbestos Joint Compound	6,553 ft ²	\$5.00/ft ²	\$32,765.00
Asbestos Wood Panel Adhesive	119,191 ft ²	\$5.00/ft ²	\$595,955.00
Asbestos Tank Insulation	445 ft ²	\$10.00/ft ²	\$4,450.00
Asbestos Mag Block Pipe Insulation	263 ft	\$25.00/ft	\$6,575.00
Asbestos Hard Fittings on Mag Block Insulation	43 ea	\$25.00/ea	\$1,075.00
Asbestos HVAC Duct Caulk	28 ft	\$10.00/ft	\$280.00
Asbestos Window Glazing	29 ea	\$225.00/ea	\$6,525.00
Asbestos Air Vent Caulk	1 ea	\$125.00/ft	\$125.00
Asbestos Penetration Putty	4 ea	\$60.00/ea	\$240.00
Asbestos Roof Flashing	7,400 ft ²	\$5.00/ft ²	\$37,000.00
Total Estimated Abatement Costs:			\$1,101,902.50

* Please refer to the note in section 2.4 "Survey Notes" for further information.

2.4 Survey Notes

A review of the data indicates the roof flashing from Seim Hall contains asbestos. Seim Hall has a built-up style roof, which may have the flashing spread across the entire surface area. LEGEND assumed the flashing to be covering the entire roof. A destructive survey should be conducted in the future, prior to renovation or demolition, to cut into the roof and verify the extent of the flashing.

ACM Orange HVAC Duct Caulk is present in the south end of room 1001. The caulk is on the duct that penetrates the south wall to the exterior; the caulk was also used to seal the duct to the wall.

LEGEND collected 1 sample of Wood Panel Adhesive from room 704E; the sample contained asbestos. The sample was collected from the south wall of the room in area where the wood paneling had peeled back from the wall. This was the only area of opportunity to sample the wood panel adhesive in the building. LEGEND assumed the adhesive to be homogeneous throughout the building and quantified the material as ACM. Due to the large quantity of wood paneling present in the building, LEGEND recommends a destructive survey be conducted prior to renovation or demolition, on a floor-by-floor basis, to inspect the wood panel adhesive and identify possible separate homogeneous areas. Any separate homogeneous areas should be sampled and analyzed to verify asbestos content.

LEGEND collected samples of Joint Compound on gypsum wallboard seams (on both walls and ceilings) throughout the building from: original vintage; a vintage from room 1; and 3 separate vintages from renovations on 1st floor. The original vintage and 1 of the vintages from first floor tested positive for asbestos. The joint compound in the southwest corner of room 1, throughout room 108, and the west wall in room 109 on 1st floor did not contain asbestos.

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 1

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	984 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	---------------------	------------------------------	------	------	--	------	---

Room 1A

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	56 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Pink Sink Undercoating	10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos sink undercoating is on the north wall.

Room 1B

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	56 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	--------------------	------------------------------	------	------	--	------	---

Room 1C

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	324 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the south windows.

Room 3

Mag Block Pipe Insulation	5-25% Chrysotile 25-35% Amosite	263 ft	Friable TSI	Damaged	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		1	The asbestos mag block pipe insulation runs along the north and east walls.
------------------------------	------------------------------------	--------	----------------	---------	--	--	---	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Hard Fittings on Mag Block Insulation	Assumed	43 fittings	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	1	None.
Tank #76-003-08 Insulation	50% Chrysotile 40% Amosite	32 ft ²	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	Tank #76-003-08 is in the northeast corner of the room.
Tank #76-003-15 Insulation	60% Chrysotile Abated January 2012	197 ft ²	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	Tank #76-003-15 is in the southeast corner of the room.
Tank #76-003-22 Insulation	60% Chrysotile Abated Nov 2010	197 ft ²	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	Tank #76-003-15 is in the southeast corner of the room.
Tank #76-003-23 Insulation	50% Chrysotile 5% Amosite	19 ft ²	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	Tank #76-003-23 is in the northeast corner of the room.

Hallway 88

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	540 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	---------------------	---------------------------	------	------	------	------	---

Room 101 (including the bathroom)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	90 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	360 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	None.
Joint Compound	2% Chrysotile	12 ft ²	Non-Friable Surfacing	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is in the bathroom on the ceiling only.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 101AB

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	192 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	560 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.
Dorm Room Ceiling Texture	3% Chrysotile	192 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 101CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	192 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	560 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.
Dorm Room Ceiling Texture	3% Chrysotile	192 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 102 (including the bathroom)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	196 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	196 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling in the bathroom.
Wood Panel Adhesive	10% Chrysotile	590 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 102AB

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 102CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.

Room 102E

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	140 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	480 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.
Dorm Room Ceiling Texture	3% Chrysotile	140 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 103

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	252 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	252 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling throughout the room.
Wood Panel Adhesive	10% Chrysotile	369 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.

Room 104

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	98 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	98 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling throughout the room.
Wood Panel Adhesive	10% Chrysotile	252 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.

Room 105 (including the bathroom)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	139 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	270 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos Wood Panel Adhesive is on the north and west walls and part of the south wall.
Dorm Room Ceiling Texture	3% Chrysotile	119 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 105AB

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic (under carpet) contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 105CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic (under carpet) contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 106

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	48 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	280 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos wall joint compound is on the east and south walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 107 (including all rooms in the apartment)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile Abated July 2011	106 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos 12" floor tile and mastic are in both bathrooms.
Joint Compound	2% Chrysotile	2,023 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceilings throughout the apartment and on several walls, refer to the ACM Locations Map.
Wood Panel Adhesive	10% Chrysotile Abated July 2011	1,840 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos adhesive is on several walls; refer to the ACM Locations Map for further information.
Pink Sink Undercoating	10% Chrysotile Removed July 2011	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos sink undercoating is in the kitchen along the north wall.

Room 108A

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	12 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	--------------------	------------------------------	------	------	--	------	---

Room 110

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	54 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	250 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling and walls.

Room 111

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	54 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	--------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Joint Compound	2% Chrysotile	250 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling and walls.

East Main Entry

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	105 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Window Glazing	2% Chrysotile	4 windows	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west windows.
Light Ceiling Texture	2% Chrysotile	105 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 None.

West Main Entry

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	105 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Window Glazing	2% Chrysotile	2 windows	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the 2 windows in the northeast corner.
Light Ceiling Texture	2% Chrysotile	105 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 None.

1st Floor Hallways (including the main lobby, both elevator lobbies, both stairway lobbies, and the southwest exit hallway)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	1,227 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	-----------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Wood Panel Adhesive	10% Chrysotile	1,750 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Light Ceiling Texture	2% Chrysotile	530 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Heavy Ceiling Texture	3% Chrysotile	543 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Heavy Wall Texture	3% Chrysotile	690 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Dorm Rooms: 201, 202, 203, 204, 205, 206, 207, 208 (including the bathrooms)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling in the bathroom only.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Dorm Rooms: 201AB, 201CD, 202AB, 202CD, 203AB, 203CD, 204AB, 204CD, 205AB, 205CD, 206AB, 206CD, 207AB, 207CD, 208AB, 208CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	------------------------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Room 204E

Wood Panel Adhesive	10% Chrysotile	270 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos adhesive is on the north, east, and west walls only.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west window.

Room 209

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the east, west, and south walls.
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Room 210

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.
------------------------------	---------------	--------------------	----------------------	------	--------------------------------------	---	---	-------

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

2nd Floor Lobby

Lobby Ceiling Texture	3% Chrysotile	538 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

Dorm Rooms: 301, 302, 303, 304, 305, 306, 307, 308 (including the bathroom)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling in the bathroom.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Dorm Rooms: 301AB, 301CD, 302AB, 302CD, 303AB, 303CD, 304AB, 304CD, 305AB, 305CD, 306AB, 306CD, 307AB, 307CD, 308AB, 308CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Room 304E

Wood Panel Adhesive	10% Chrysotile	430 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos window glazing is on the west window.

Room 309

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*	N/A*	The asbestos joint compound is on the east, west, and south walls.
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 None.

Room 310

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 None.
------------------------------	---------------	--------------------	----------------------	------	--------------------------------------	---	------------

3rd Floor Lobby

Lobby Ceiling Texture	3% Chrysotile	845 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 Refer to the ACM Locations Map for further information.
-----------------------	---------------	---------------------	----------------------	------	--------------------------------------	---	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.

Dorm Rooms: 401, 402, 403, 404, 405, 406, 407, 408 (including the bathrooms)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.
Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the ceiling in the bathrooms.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Dorm Rooms: 401AB, 401CD, 402AB, 402CD, 403AB, 403CD, 404AB, 404CD, 405AB, 405CD, 406AB, 406CD, 407AB, 407CD, 408AB, 408CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 404E

Wood Panel Adhesive	10% Chrysotile	430 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west window.
12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	128 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.

Room 409

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the east, west, and south walls.
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.

Room 410

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.
------------------------------	---------------	--------------------	----------------------	------	--	--	---	-------

4th Floor Lobby

Light Ceiling Texture	3% Chrysotile	538 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	Refer to the ACM Locations Map for further information.
-----------------------	---------------	---------------------	----------------------	------	--	--	---	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

Dorm Rooms: 501, 502, 503, 504, 505, 506, 507, 508 (including the bathrooms)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling in the bathrooms.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Dorm Rooms: 501AB, 501CD, 502AB, 502CD, 503AB, 503CD, 504AB, 504CD, 505AB, 505CD, 506AB, 506CD, 507AB, 507CD, 508AB, 508CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 504E

Wood Panel Adhesive	10% Chrysotile	430 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west window.

Room 509

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the east, west, and south walls.
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.

Room 510

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.
------------------------------	---------------	--------------------	----------------------	------	--	--	---	-------

5th Floor Lobby

Light Ceiling Texture	3% Chrysotile	845 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

Dorm Rooms: 601, 602, 603, 604, 605, 606, 607, 608 (including the bathrooms)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling in the bathrooms.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.

Dorm Rooms: 601AB, 601CD, 602AB, 602CD, 603AB, 603CD, 604AB, 604CD, 605AB, 605CD, 606AB, 606CD, 607AB, 607CD, 608AB, 608CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 604E

Wood Panel Adhesive	10% Chrysotile	430 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west window.
12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	128 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.

Room 609

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the east, west, and south walls.
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.

Room 610

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.
------------------------------	---------------	--------------------	----------------------	------	--	--	---	-------

6th Floor Lobby

Light Ceiling Texture	3% Chrysotile	538 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	The asbestos light ceiling texture is in the hallways next to the dorm rooms.
-----------------------	---------------	---------------------	----------------------	------	--	--	---	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.

Dorm Rooms: 701, 702, 704, 705, 706, 707, 708 (including the bathrooms)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.
Ceiling Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*	N/A*	N/A*	The asbestos ceiling joint compound is in the closet only.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.

Dorm Rooms: 701AB, 701CD, 702AB, 702CD, 703AB, 703CD, 704AB, 704CD, 705AB, 705CD, 706AB, 706CD, 707AB, 707CD, 708AB, 708CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	None.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Dorm Room 703 (including the bathroom)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	90 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Mastic for 12" Beige Floor Tile	2% Chrysotile	16 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative. It is in the bathroom.
Wood Panel Adhesive	10% Chrysotile	440 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Ceiling Joint Compound	2% Chrysotile	16 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos ceiling joint compound is in the closet only.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None.

Room 704E

Wood Panel Adhesive	10% Chrysotile	430 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west window.

Room 709

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the east, west, and south walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Room 710

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.
------------------------------	---------------	--------------------	----------------------	------	--------------------------------------	---	---	-------

7th Floor Lobby

Light Ceiling Texture	3% Chrysotile	845 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.

Dorm Rooms: 801, 802, 803, 804, 805, 806, 807, 808 (including the bathrooms)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.
Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the ceilings in the bathrooms.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Dorm Rooms: 801AB, 801CD, 802AB, 802CD, 803AB, 803CD, 804AB, 804CD, 805AB, 805CD, 806AB, 806CD, 807AB, 807CD, 808AB, 808CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 None.

Room 804E

Wood Panel Adhesive	10% Chrysotile	430 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	Refer to the ACM Locations Map for further information.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos window glazing is on the west window.
12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	128 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.

Room 809

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	--------------------	------------------------------	------	------	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the east, west, and south walls.
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Room 810

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.
------------------------------	---------------	--------------------	----------------------	------	--------------------------------------	---	---	-------

8th Floor Lobby

Lobby Ceiling Texture	3% Chrysotile	538 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

Dorm Rooms: 901, 902, 903, 904, 905, 906, 907, 908 (including the bathrooms)

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	106 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	440 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Joint Compound	2% Chrysotile	16 ft ² each	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling in the bathrooms.
Dorm Room Ceiling Texture	3% Chrysotile	90 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Dorm Rooms: 901AB, 901CD, 902AB, 902CD, 903AB, 903CD, 904AB, 904CD, 905AB, 905CD, 906AB, 906CD, 907AB, 907CD, 908AB, 908CD

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	168 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Wood Panel Adhesive	10% Chrysotile	520 ft ² each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Dorm Room Ceiling Texture	3% Chrysotile	168 ft ² each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Room 904E

Wood Panel Adhesive	10% Chrysotile	430 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
Window Glazing	2% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west window.

Room 909

12" Tan Floor Tile w/ Brown Streaks and Mastic	3-15% Chrysotile	32 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
--	------------------	--------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Joint Compound	2% Chrysotile	320 ft ²	Non-Friable Surfacing	N/A*	N/A*		N/A*	The asbestos joint compound is on the east, west, and south walls.
Dorm Room Ceiling Texture	3% Chrysotile	32 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.

Room 910

Dorm Room Ceiling Texture	3% Chrysotile	45 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
---------------------------	---------------	--------------------	-------------------	------	--------------------------------------	---	---	---

9th Floor Lobby

Lobby Ceiling Texture	3% Chrysotile	810 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None.
Heavy Wall Texture	3% Chrysotile	600 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos heavy wall texture is along the elevator walls and stairway entrances.
Wood Panel Adhesive	10% Chrysotile	1,260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

Room 1001

Orange HVAC Duct Caulk	3% Chrysotile	28 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos caulk is on the ducts on the south end of the room and is also around the duct where it penetrates the wall.
------------------------	---------------	-------	---------------------------	------	------	--	------	---

Exterior

Window Glazing	2% Chrysotile	13 windows	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is off of rooms 103, 108, east main entry, and west main entry.
----------------	---------------	------------	---------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SEIM HALL (BLDG A076)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Air Vent Caulk	3% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos air vent caulk is along the south side of the penthouse (on the roof).
Penetration Putty (on cables)	25% Chrysotile	4 each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos penetration putty is along the north, east, and west sides of the penthouse (on the roof).

Roof Removed during reroof Summer

Roof Flashing	3% Chrysotile	7,400 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to section 2.4 "Survey Notes" for further information.
---------------	---------------	-----------------------	------------------------------	------	------	--	------	--

¹Assessment Categories:

- | | |
|--|---|
| <ul style="list-style-type: none"> 1) Damaged or Significantly Damaged TSI ACM 2) Damaged Friable Surfacing ACM 3) Significantly Damaged Friable Surfacing ACM 4) Damaged or Significantly Damaged Friable Miscellaneous ACM | <ul style="list-style-type: none"> 5) ACM with Potential for Damage 6) ACM with Potential for Significant Damage 7) Any Remaining Friable ACM or Friable Suspected ACM |
|--|---|

End