


2005 SURFACE MINING REPORT



**For Minerals
Other Than Coal**

PREPARED BY: ND STATE SOIL CONSERVATION COMMITTEE - BISMARCK, ND

SUMMARY OF SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 2004.

There were 15 surface mining operators reporting for the calendar year 2005. The following are approximate total operations according to the reports submitted:

1. Acres affected	240.2	
2. Minerals mined		
A) Gravel & Sand	2,298,093	cubic yards
B) Clay	77,500	cubic yards
C) Rock	31,259	cubic yards
D) Scoria	33,254	cubic yards
TOTAL	2,440,106	cubic yards
3. Overburden disturbed	687,262	cubic yards

There are 55 pits ranging in size from .5 to 20 acres. Minerals mined were gravel, sand, clay, rock and scoria.

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	7-11-05	8-11-05	Pioneer Construction, Inc. 4025 Co Rd 82 Mandan, ND 58554	Edward Heinze Dazey, ND 58428
Overburden was regraded and topsoil was respread	5-1-05	12-1-05	Hilltop Sand & Gravel, Inc. 3520 Kathryn Road S Valley City, ND 58072	Gwen Blumer 3520 Kathryn Rd S Valley City, ND 58072
Overburden was regraded and topsoil was respread	6-18-05	8-23-05	Fisher Sand & Gravel PO Box 1034 Dickinson, ND 58602	State of North Dakota
	5-20-05	11-8-05	Benson County PO Box 184 Minnewaukan, ND 58351	Bryan Britsch 4726 53rd St NE York, ND 58386
	9-16-05	11-7-05	Benson County PO Box 184 Minnewaukan, ND 58351	Jarris Hegland 6078 31st St NE Oberon, ND 58357
	10-15-05	11-1-05	Benson County PO Box 184 Minnewaukan, ND 58351	David Hoffert 5679 39th Ave NE Rugby, ND 58368
			Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Leelyn Hermanson PO Box 14 Lignite, ND 58752
	6-13-05	7-13-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Les Mariner 8049 Co Rd 16 Kernmare, ND 58746
	11-7-05	12-12-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Mark Carlson 8250 99th Ave NW Battleview, ND 58773
	11-7-05	12-12-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Roger Moberg 995 Hwy 50 Powers Lake, ND 58773
	8-25-05	9-2-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Gerdie Johnson, Estate Lignite, ND 58752

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (M/D/Y/R)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	7-13-05	7-29-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Lucy Estate Powers Lake, ND 58773
	4-25-05	5-26-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Brian Ankenbauer 9195 Co Rd 17 Bowbells, ND 58721
Overburden was regraded and topsoil was respread	3-1-05	5-20-05	Fisher Sand & Gravel PO Box 1034 Dickinson, ND 58602	Allan Whitman 36850 Hwy 10 Driscoll, ND 58532
Overburden was regraded and topsoil was respread	4-6-05	4-26-05	Pioneer Construction, Inc. 4025 Co Rd 82 Mandan, ND 58554	Monte Dralle 10002 275th St NE Sterling, ND 58572
Overburden was regraded and topsoil was respread	11-4-05	12-14-05	Fisher Sand & Gravel PO Box 1034 Dickinson, ND 58602	Wesley Ewine 1618 N 26th St Bismarck, ND 58501
Overburden was regraded and topsoil was respread	5-7-01	11-7-05	Northern Improvement Comapny PO Box 1254 Bismarck, ND 58502	Northern Improvement Company PO Box 1254 Bismarck, ND 58502
	10-19-05	11-7-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Lowell Eide Williston, ND 58901
	9-2-05	9-22-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Larry Lee PO Box 169 Crosby, ND 58730
	9-22-05	10-19-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Neil Riveland Williston, ND 58801
Overburden was regraded to approximate original topography and topsoil was respread	4-7-05	7-8-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Arnold Skachenko 139 107th Ave NW Killdeer, ND 58640
	11-12-05	1-5-06	Holen Construction, Inc. PO Box 319 McClusky, ND 58463	Holen Construction, Inc. PO Box 319 McClusky, ND 58463

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded			Harley & Judy Camperud 2732 6th Ave Northwood, ND 58267	Grensrich Farms Rural Route Northwood, ND 58267
			Harley & Judy Camperud 2732 6th Ave Northwood, ND 58267	Robert Lenz 1951 5th Ave Thompson, ND 58278
			Pioneer Construction, Inc. 4025 Co Rd 82 Mandan, ND 58554	Ron Rewald 1945 46th Ave SE Pettibone, ND 58475
Overburden was regraded to approximate topography and topsoil was respread	6-13-05	7-8-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58072	Judith Dugger 694 N 400 E Valparaiso, IN 46383
Overburden was regraded to approximate topography and topsoil was respread	4-20-05	7-29-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58072	Eldryce Hansen 6686 22nd Ave N Deering, ND 58731
Overburden was regraded to approximate topography and topsoil was respread	5-16-05	6-17-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Lynn Kongsle 45 54th St NE Tower, ND 58788
Overburden was regraded to approximate topography and topsoil was respread	7-27-05	8-6-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Shirley Raile 14941 E Valley View Dr Piedmont, ND 57769
Overburden was regraded to approximate topography and topsoil was respread	7-11-05	8-24-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58072	Paul Wood 1659 26th Ave NW Coleharbor, ND 58531
Overburden was regraded to approximate topography and topsoil was respread	4-1-05	5-11-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58072	Paul Wood 1659 26th Ave NW Coleharbor, ND 58531
Overburden was regraded to approximate topography and topsoil was respread	9-16-05	12-2-05	Northern Improvement Company PO Box 1254 Bismarck, ND 58502	Great River Energy 2875 Third St SW Underwood, ND 58576
Overburden was regraded to approximate topography and topsoil was respread	8-30-05	9-10-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Herbert Shafer 2480 58th Ave NW Roseglen, ND 58775
Overburden was regraded to approximate topography and topsoil was respread	9-30-05	11-30-05	The Coteau Properties Company 204 Co Rd 15 Beulah, ND 58523	The Coteau Properties Company 204 Co Rd 15 Beulah, ND 58523

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to approximate topography and topsoil was respread	1-31-05	12-31-05	The Coteau Properties Company 204 Co Rd 15 Beulah, ND 58523	The Coteau Properties Company 204 Co Rd 15 Beulah, ND 58523
Overburden was regraded to approximate topography and topsoil was respread	6-26-05	7-29-05	Fisher Sand & Gravel PO Box 1034 Dickinson, ND 58602	Pioneer Construction, Inc. 4025 Co Rd 82 Mandan, ND 58554
Overburden was regraded to approximate topography and topsoil was respread	5-6-05	5-19-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Larry Thronson PO Box 455 Powers Lake, ND 58773
Overburden was regraded to approximate topography and topsoil was respread	9-22-05	10-20-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Daniel Joyce 310 S Main Toga, ND 58852
Overburden was regraded to approximate topography and topsoil was respread	5-9-05	9-17-05	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Clyde Schmidt Minot, ND 58702
Overburden was regraded to approximate topography and topsoil was respread	8-16-05	8-25-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58072	Nancy Schmidt 17 20th St NW Minot, ND 58703
Overburden was regraded to approximate topography and topsoil was respread	6-24-05	9-1-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Willard Hanson 6277 99th Ave NW White Earth, ND 58794
Overburden was regraded to approximate topography and topsoil was respread	6-20-05	8-16-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Don Heinle 225 St NW Tioga, ND 58852
Overburden was regraded to approximate topography and topsoil was respread	1960		Hebron Brick Company 1000 E Washington Ave Hebron, ND 58638	Mary Rolf PO Box 697 Stanley, ND 58784
Overburden was regraded to approximate topography and topsoil was respread	1970		Hebron Brick Company 1000 E Washington Ave Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638
Overburden was regraded to approximate topography and topsoil was respread	1970		Hebron Brick Company 1000 E Washington Ave Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/R)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	1954		Hebron Brick Company 1000 E Washington Ave Hebron, ND 58638	Hebron Brick Company 1000 E Washington Ave Hebron, ND 58638
	2005		Susag Sand & Gravel, Inc. PO Box 23 Harvey, ND 58341	Marie Deck 2851 35th St NE Harvey, ND 58341
	3-9-05	3-30-05	Pioneer Construction, Inc. 4025 Co Rd 82 Mandan, ND 58554	Moldenhauer Properties 8600 66th Ave SE Minot, ND 58701
Overburden was regraded to approximate topography and topsoil was respread	9-6-05	10-10-05	Fisher Sand & Gravel PO Box 1034 Dickinson, ND 58602	Pioneer Construction, Inc. 4025 Co Rd 82 Mandan, ND 58554
	8-15-05	9-2-05	Pioneer Construction, Inc. 4025 Co Rd 82 Mandan, ND 58554	Paul Heer 3919 23rd Ave SE Jamestown, ND 58401
Overburden was regraded	1961		Miller Gravel & Ready Mix, Inc. PO Box 728 Cando, ND 58324	Roger Miller PO Box 728 Cando, ND 58324
	1-1-05	12-31-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701
Overburden was regraded to approximate topography and topsoil was respread	5-13-05	11-19-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58072	John Novodvorsky 23101 114th St SW Douglas, ND 58735
	9-14-05	9-24-05	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Gene Schoenberg 17000 345th Ave SE Benedict, ND 58716
Overburden was regraded to approximate topography and topsoil was respread	7-6-05	7-11-05	Aggregate Construction, Inc. PO Box 239 Minot, ND 58072	Duane & Donna Gafken 1124 6th Ave E Williston, ND 58801
			Kulland Excavating & Gravel Inc. 1505 58th St W Williston, ND 58801	Kenneth Heen 410 17th St W Williston, ND 58801

