


1999

# SURFACE MINING REPORT



**For Minerals  
Other Than Coal**

## SUMMARY OF SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 1999.

There were 17 surface mining operators reporting for the calendar year 1999. The following are approximate total operations according to the reports submitted:

1.	Acres affected	310	
2.	Minerals mined		
	A) Gravel & Sand	3,536,027	cubic yards
	B) Clay	88,660	cubic yards
	C) Rock	141,429	cubic yards
	D) Scoria	2,190	cubic yards
	TOTAL	3,768,306	cubic yards
3.	Overburden disturbed	747,876	cubic yards

There are 61 pits ranging in size from .3 to 55 acres. Minerals mined were gravel, sand, clay, rock and scoria.

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3814 (12/85)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAYR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Reclamation is being completed as areas are mined	6-99	7-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Betsy Illes 111 Murray Court Escondido, CA
	7-99	10-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Matt Locken HCR 1, Box 49 Pekin, ND 58361
Overburden was regraded and topsoil respread	3-29-99	12-17-99	Hilltop Sand & Gravel Inc. 3520 Kathryn Road S Valley City, ND 58072	Gwen Blumer 3520 Kathryn Road S Valley City, ND 58072
	5-25-99	8-9-99	Benson County Hwy Dept. PO Box 184 Minnewaukan, ND 58351	Kenneth Vetsch 3673 49th Street NE Esmond, ND 58332
	8-10-99	10-7-99	Benson County Hwy Dept. PO Box 184 Minnewaukan, ND 58351	Archie Rohrer Trust 12th Avenue S Devils Lake, ND 58301
	10-11-99	11-30-99	Benson County Hwy Dept. PO Box 184 Minnewaukan, ND 58351	Brian Britsch 4726 53rd Street NE York, ND 58386
	11-15-99	12-3-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Johnny Roos 1515 17th Avenue SW Minot, ND 58701
	8-30-99	9-7-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Leelyn Hermanson PO Box 14 Lignite, ND 58752
Overburden was regraded	8-20-99	8-27-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Victor Hoff 9232 93rd Street SW Columbus, ND 58727
Overburden was regraded to approximate original topography and topsoil was respread	4-22-99	6-2-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Victor Hoff 9232 93rd Street SW Columbus, ND 58727
Reclamation is being completed as gravel is removed	9-1-99		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Johnson Pit 1511 Pocattello Drive Bismarck, ND 58501

ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3814 (12/85)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAYR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	10-22-99	11-23-99	Bernard Mahner Construction Inc. PO Box 57 Rutland, ND 58067	Glynn Farms Fullerton, ND 58441
Overburden was regraded and topsoil respread	7-12-99	7-27-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Stanly Krupsky 8721 94th Avenue SE Fullerton, ND 58441
Reclaimed to pastureland	9-17-99	10-21-99	Bernard Mahner Construction Inc. PO Box 57 Rutland, ND 58067	Kaiser Pit Ellendale, ND 58436
Overburden was regraded	7-28-99	8-14-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Harold Johanson Wesby, MT
Overburden was regraded	9-7-99	9-20-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Harold Westin HCR 1, Box 22 Alamo, ND 58830
	9-21-99	10-1-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Lowell Eide HCR 2, Box 22 Williston, ND 58901
Overburden was regraded	10-4-99	10-11-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Bruce Verlinde PO Box 88 Noonan, ND 58765
Overburden was regraded	7-6-99	7-26-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Dennis Slaaen HC 2, Box 17 Grenora, ND 58845
Overburden was regraded	8-8-99	8-19-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Raymond Riveland 2009 20th Avenue W Williston, ND 58801
Overburden was regraded	10-12-99	10-25-99	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Arvid Olson HC 1, Box 24 McGregor, ND 58755
	7-1-95		Holen Construction Inc. PO Box 126 McClusky, ND 58463	Allen & Ellen Messner Rural Route Sheyenne, ND 58374

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3814 (12/85)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAYR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded			Camperud Gravel Supply 2732 6th Avenue Northwood, ND 58267	Genstrich Farms Rural Route Northwood, ND 58267
Overburden was regraded			Camperud Gravel Supply 2732 6th Avenue Northwood, ND 58267	Robert Lenz Rural Route Thompson, ND 58278
Topsoil was respread			Bernard Mahrer Construction Inc. PO Box 57 Rutland, ND 58067	Green Acre Farms Oakes, ND 58474
	8-19-99	9-16-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Philp Seefeldt 6597 98th Avenue SE Lamoure, ND 58458
	5-3-99	7-6-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Marvin Neumiller RT 1, Box 23 Washburn, ND 58577
	5-15-99	10-16-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Nathan Strelker 327 Hwy 83 S Washburn, ND 58577
Overburden was regraded	11-99	12-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Robert Ash RT 1 Underwood, ND 58576
Overburden was regraded and topsoil was respread	5-1-99	11-6-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Glenn Matton 8131 Hobart Drive Zephyrhills, FL 33540
Overburden was regraded and topsoil was respread	10-2-99	10-30-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Don Streifel 1076 B Hwy 83 S Washburn, ND 58577
Overburden was regraded to approximate original topography	4-26-99	7-29-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	5-1-99	10-1-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	Rueben Scheid 500 1st Street NW Beulah, ND 58523
	6-1-99	9-11-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3814 (12/85)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/R)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/Completed		
	6-1-99	9-11-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	Ray Galster 5680 County 26 Beulah, ND 58523
	6-1-99	9-11-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	Robert Scheid 158 County 27 Hazen, ND 58545
	10-1-99	10-31-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	6-1-99	9-11-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	Ricky Scheid 15 55th Avenue NW Hazen, ND 58545
	6-1-99	9-11-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	Elroy Wolf 5475 3rd Street SW Hazen, ND 58545
	6-1-99	9-1-99	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
Overburden was regraded to approximate original topography	1960		Hebron Brick Company PO Box S Hebron, ND 58638	Wayne Petri PO Box S Hebron, ND 58638
Overburden was regraded to approximate original topography	1970		Hebron Brick Company PO Box S Hebron, ND 58638	Wayne Petri PO Box S Hebron, ND 58638
Overburden was regraded to approximate original topography	1954		Hebron Brick Company PO Box S Hebron, ND 58638	Hebron Brick Company PO Box S Hebron, ND 58638
Reclamation is being completed as gravel is removed	4-1-99		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Meidinger PO Box 566 Mandan, ND 58554
Reclamation is being completed as gravel is removed	1-13-99		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Jacobson 2890 Hwy 25 Mandan, ND 58554

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3814 (12/85)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAYR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to approximate original topography and topsoil was respread	7-26-99	9-9-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Henry Miller HC 2, Box 283 Center, ND 58530
Overburden was regraded to approximate original topography and topsoil was respread	8-13-99	9-27-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Reynard Schmidt HC 2, Box 173 Center, ND 58530
Overburden was regraded to approximate original topography and topsoil was respread	8-8-99	8-18-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	John Yantzer 1908 12th Avenue SE Mandan, ND 58554
	6-8-98		Mike Ausiford & Sons Inc. 13709 Hwy 5 Cavalier, ND 58220	Ceciel & Paul Sigurdson 600th Street S Edinburg, ND 58227
	1999		Susag Sand & Gravel Inc. PO Box 23 Harvey, ND 58341	Marie Deck 233 Jackson Avenue Harvey, ND 58341
Topsoil was respread	5-19-99	11-30-99	Soper Construction PO Box 791 Devils Lake, ND 58301	Townships in Ramsey County
Topsoil was respread	11-24-99	12-9-99	Bernard Mahler Const. Inc. 201 First Street, PO Box 57 Rutland, ND 58067	Keith Hoistad 14027 74th Street SE Milnor, ND 58060
Overburden was regraded and topsoil was respread	4-99	6-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Gerald Lutman Carrington, ND 58421
Topsoil was respread			Lindberg Brothers Inc. PO Box 2115 Jamestown, ND 58402	Gayne Gasal RR 1, Box 242 Jamestown, ND 58402
Overburden was regraded	5-1-61		Roger L. Miller - Miller Gravel PO Box 728 Cando, ND 58324	Roger L. Miller PO Box 728 Cando, ND 58324
	10-12-99	10-20-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Eugene Livingston RR 1, Box 32 Surrey, ND 58785

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3814 (1/2/85)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to approximate original topography and topsoil was respread	1-1-99	12-31-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	General Steel & Supply Co. PO Box 1034 Dickinson, ND 58602
	2-8-99	3-5-99	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	General Steel & Supply Co. PO Box 1034 Dickinson, ND 58602
	5-99		Kulland Excavating & Gravel Inc. 1505 58th Street W Williston, ND 58901	Kermit Smith 1310 Hill Court Williston, ND 58901
	7-15-99	12-1-99	Vizina's Ready Mix PO Box 108 Williston, ND 58901	Dale Moline 6103 Hwy 85 Williston, ND 58901