


# 2010 SURFACE MINING REPORT



**For Minerals  
Other Than Coal**

PREPARED BY: ND STATE SOIL CONSERVATION COMMITTEE - BISMARCK, ND

## SUMMARY OF SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 2010.

There were 17 surface mining operators reporting for the calendar year 2010. The following are approximate total operations according to the reports submitted:

<b>1.</b>	<b>Acres affected</b>	<b>339.1</b>	
<b>2.</b>	<b>Minerals mined</b>		
	A) Gravel & Sand	3,876,363	cubic yards
	B) Clay	26,505	cubic yards
	C) Scoria	96,531	cubic yards
	D) Rock	29,506	cubic yards
	<b>TOTAL</b>	<b>4,000,067</b>	<b>cubic yards</b>
<b>3.</b>	<b>Overburden disturbed</b>	<b>326,619</b>	<b>cubic yards</b>

There are 73 pits ranging in size from .5 to 40 acres. Minerals mined were gravel, sand, clay, scoria and rock.

# SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2010  
 ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Town- ship	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Adams	8	132	97	Gravel	11.0	50,700		15'	Rangeland	Pastureland
Barnes	12	143	58	Gravel	11.0	40,500		15'	Rangeland	Pastureland
Benson	1	154	71	Gravel	15.0	40,500		15'	Rangeland	Pastureland
	30	151	67	Gravel	2.0	22,911	800		Improved Pasture	
Bowman	32	132	104	Sand Gravel	4.0	38,720	9,220	12'	Rangeland	Pastureland
Burke	3	159	90	Gravel	2.0	15,000	3,000			
	7	160	94	Gravel	2.0	14,728	1,000	10'	Rangeland	Pastureland
	21	159	94	Sand Gravel	4.5	41,330	3,630	12'	Gravel Pit Rangeland	Wildlife Habitat Industrial
	22	161	93	Gravel	5.0	39,815	3,000	10'	Gravel Pit	
	24	161	93	Gravel	2.0	10,366	500	10'	Gravel Pit	Industrial
	25	161	91	Gravel	1.0	7,627		10'	Gravel Pit	

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Topsoil was respread and leveled	9/11/2010	10/4/2010	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Tim Milliren 1902 10th St. NW Reeder, ND 58649
	5/18/2010	6/11/2010	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Betsy Illies Sibley, ND 58429
Topsoil was respread and leveled	7/22/2010	8/26/2010	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Derold Simonson 5195 42nd Ave. NE Esmond, ND 58332
			Benson County Hwy Dept. PO Box 184 Minnewaukan, ND 58351	Jarvis Hegland 6078 31st St. NE Oberon, ND 58357
Overburden was regraded and topsoil was respread	4/18/2010	6/5/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Jerome Fischer 8304 160th Ave. SW Rhame, ND 58651
	8/31/2010	10/4/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Randy Edwards Box 106 Kenmare, ND 58746
Overburden was regraded and topsoil was respread	8/9/2010	8/31/2010	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Erling Barmoen 6980 102nd Ave. NW Toga, ND 58852
Overburden was regraded and topsoil was respread	9/27/2010	10/25/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Roger Moberg 9995 Hwy 50 Battleview, ND 58773
Overburden was regraded and topsoil was respread	5/3/2010	11/12/2010	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Roger Dollarhide 1891 Virginia Ave. McLean, VA 22101
Overburden was regraded, topsoil was respread and area was seeded with grass	7/21/2010	8/5/2010	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Orten Oas 9250 County Rd 7 Columbus, ND 58752
Overburden was regraded	9/9/2010	10/6/2010	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Earl Chrest Jr. 9151 79th Ave. NW Bowbells, ND 58721

# SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2010  
 ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Town- ship	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Burke	35	160	91	Gravel	1.0	10,000		10'	Hayland	Pastureland
Burleigh	28	140	77	Gravel				8'	Rangeland	Pastureland
	28	140	77	Sand Gravel	12.0	150,000	15,000	8'	Hayland	Pastureland Cropland
Eddy	5	150	66	Gravel	15.0	90,000	7,500	10'	Hayland	Cropland
	6	150	66	Gravel	40.0	255,000	15,000	12'	Hayland Rangeland	Pastureland Cropland Wildlife Habitat
Grand Forks	8	149	52	Sand Gravel		5,478	20	8'		Wildlife Habitat
	12	149	52	Rock		668		6'		Pastureland
Kidder	12	139	71	Gravel	8.0	41,000		15'	Rangeland	Pastureland
	24	137	70	Sand Gravel	3.8	37,037	5,598	8'	Hayland	Hayland
	33	141	72	Sand Gravel	1.0	18,518	605	15'	Hayland	Hayland
	34	137	71	Sand Gravel	2.2	27,407	1,331	10'	Hayland	Hayland

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAYR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	11/17/2010	12/10/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Robert Neuenfeld Box 516 Kenmare, ND 58746
Reclamation is current	5/13/2010		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
Overburden was regraded and topsoil was respread	5/7/2010		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
	10/15/2010	12/1/2010	Gowan Construction, Inc. PO Box 228 Oslo, MN 56744	Beverly Soderholm 7456 29th St. NE Sheyenne, ND 58374
Overburden was regraded	4/29/2010		Gowan Construction, Inc. PO Box 228 Oslo, MN 56744	Arlene Benson Sunnyside Ave. Sheyenne, ND 58374
			Harley & Judy Camperud 2732 6th Ave. Northwood, ND 58267	Grensrich Farms Rural Route Northwood, ND 58267
			Harley & Judy Camperud 2732 6th Ave. Northwood, ND 58267	Robert Lentz 1951 5th Ave. Thompson, ND 58278
	4/8/2010	5/11/2010	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	
Topsoil was respread	9/10/2010	9/28/2010	Hoffer Sand & Gravel 5353 40th Ave. SE Tappen, ND 58487	Gary Bonnet 5191 48th Ave. SE Streeter, ND 58483
Topsoil was respread	6/10/2010	6/22/2010	Hoffer Sand & Gravel 5353 40th Ave. SE Tappen, ND 58487	James Brousseau 3130 30th Ave. SE Steele, ND 58482
Topsoil was respread	7/26/2010	8/7/2010	Hoffer Sand & Gravel 5353 40th Ave. SE Tappen, ND 58487	Bill Hoffer 5353 40th Ave. SE Tappen, ND 58487

# SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2010  
 ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Sec- tion	Town- ship	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Logan	5	135	67	Sand Gravel	9.7	41,500	31,300	10'	Gravel Pit Rangeland	Pastureland
	6	133	68	Sand Gravel	2.2	24,006	1,331	9'	Hayland	Hayland
McHenry	4	155	79	Sand Gravel	2.0	11,000		12'	Gravel Pit	Wildlife Habitat
	13	153	80	Sand Gravel	4.0	54,700		15'	Gravel Pit	Pastureland
	29	157	80	Sand Gravel	2.1	21,200	6,100	7'	Hayland Gravel Pit	Hayland
	31	156	76	Sand Gravel	6.3	121,100	30,300	12'	Gravel Pit	Pastureland
McKenzie	6	151	103	Sand Gravel	3.8	84,000	50,000	45'	Rangeland	Pastureland Wildlife Habitat
	23	149	98	Clay Scoria	2.0	1,414 36,035	9,680	16'	Gravel Pit Rangeland	
	25	152	101	Scoria	2.0	18,496	1,613	12'	Gravel Pit Rangeland	
	32	151	96	Scoria	2.0	42,000	2,000		Cropland	
McLean	7	149	86	Gravel	6.0	75,000	8,000	15'	Hayland	Pastureland

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to approximate original topography and topsoil was respread	8/27/2010	9/21/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Don Boehmer 5992 Hwy 56 Gaacke, ND 58442
Topsoil was respread	10/19/2010	11/8/2010	Hoffer Sand & Gravel 5353 40th Ave. SE Tappen, ND 58487	Darryl Buchholz 7361 54th Ave. SE Lehr, ND 58460
	5/1/2010	6/18/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Judith Dugger 694 N 400 E Valparaiso, IN 46383
	8/24/2010	9/30/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Curt Feist PO Box 42 Velva, ND 58790
	6/10/2010	6/25/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Eldryce Hansen 6686 22nd Ave. N Deering, ND 58731
	7/9/2010	8/27/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Jonathan Eaton 807 13th St. NW Minot, ND 58701
Overburden was regraded to approximate original topography and topsoil was respread	6/30/2010	7/31/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	James Guilkson 3492 157th Ave. NW Cartwright, ND 58838
	4/15/2010		Three Way, Inc. PO Box 250 Buffalo, WY 82834	Randy Stevenson 2131 122nd Ave. NW Watford City, ND 58854
	7/1/2010		Three Way, Inc. PO Box 250 Buffalo, WY 82834	Daniel Abeilmann 3382 Hwy 85 N Alexander, ND 58831
	5/20/2010	11/17/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Larry Signalness 2961 Hwy 23 Watford City, ND 58854
Overburden was regraded and topsoil was respread	7/26/2010		Fisher Sand & Gravel Co. 3020 Energy Dr. Dickinson, ND 58601	John Haugen 2263 55th Ave. NW Roseglen, ND 58775



# SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2010  
 ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
McLean	7	149	86	Gravel	10.0	600,000	120,000	15'	Hayland	Pastureland
	22	149	80	Sand Gravel	1.4	37,000	3,500	16'	Cropland	Cropland
	25	149	82	Sand Gravel	3.1	22,900	5,000	8'	Cropland	Cropland
	30	144	80	Gravel	5.0	30,000	3,000	10'		Cropland
Mountrail	5	154	93	Gravel	5.0	40,000	3,000		Improved Pasture	
	12	152	92	Gravel	5.0	110,000	25,000	11'	Hayland	Pastureland
	14	154	89	Sand Gravel	1.8	25,000	1,815	15'	Rangeland	Wildlife Habitat
	14	154	89	Sand Gravel	3.0	55,000	4,840	14'	Rangeland	Pastureland
	15	153	91	Sand Gravel	4.5	43,970	7,200	13'	Cropland	Cropland
	20	153	89	Sand Gravel	3.5	31,425	5,650	20'	Cropland Rangeland	Cropland Wildlife Habitat
	21	156	90	Sand Gravel	1.8	39,285	4,100	15'	Rangeland	Wildlife Habitat

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	7/26/2010		Fisher Sand & Gravel Co. 3020 Energy Dr. Dickinson, ND 58601	Jack Gerwing 2260 53rd Ave. NW Ryder, ND 58779
	10/5/2010	10/14/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Roger Kramme 2044 15th Ave. NW Ruso, ND 58778
	10/12/2010	10/19/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Matt Boukoon Estate PO Box 23 Coleharbor, ND 58531
	8/15/2008		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Shirley Jennings 3802 Normandy St. Bismarck, ND 58503
	6/8/2010	7/29/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Kevin Lapica 9027 56th St. NW Ross, ND 58776
Overburden was regraded and topsoil was respread	6/26/2010		Fisher Sand & Gravel Co. 3020 Energy Dr. Dickinson, ND 58601	Dale Estvold 4011 84th Ave. NW New Town, ND 58763
	8/2/2010	8/8/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	James Edwards PO Box 187 Plaza, ND 58771
Overburden was regraded and topsoil was respread	5/10/2010	5/28/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	James Edwards PO Box 187 Plaza, ND 58771
	7/12/2010	7/29/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Norris Welfen 7751 45th St. NW New Town, ND 58763
Overburden was regraded	8/9/2010	8/14/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	John Bartleson Jr. 4340 71st Ave. NW Parshall, ND 58770
Overburden was regraded and topsoil was respread	4/1/2010	4/10/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Nancy Schmidt 17 20th St. NW Minot, ND 58703

# SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2010  
 ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3813 (10/2003)

County	LOCATION OF MINING OPERATION			Type of Mineral Mined	CURRENT YEAR OPERATIONS			Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
	Section	Township	Range		Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Mountrail	26	156	94	Sand Gravel	8.5	114,300	13,710	40'	Rangeland	Pastureland Wildlife Habitat
	29	152	92	Sand Gravel	9.8	124,100	24,100	8'	Cropland	Cropland
	30	156	88	Gravel	1.0	18,000			Improved Pasture	Pastureland
	32	156	91	Sand Gravel	3.6	43,000	10,165	20'	Rangeland	Cropland Wildlife Habitat
Morton	4	140	90	Clay	1.0	4,646	8,000	55'	Rangeland	Pastureland
	10	140	90	Clay	1.0	6,731	1,000	30'	Cropland	Cropland
	11	140	90	Clay	2.0	13,714	25	25'		Pastureland
Oliver	14	141	81	Gravel				8'	Rangeland	Pastureland
	5	162	56	Gravel	0.8	17,825	1,500	15'	Cropland	
Pierce	30	152	72	Gravel	3.0	20,000	400	18'	Cropland	Cropland Wildlife Habitat
	7	162	86	Gravel	0.5	20,000	1,000		Pasture	

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	10/22/2010	12/31/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Dale Lalim Box 638 Tloga, ND 58852
Overburden was regraded	7/31/2010	11/19/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Kenneth Reynolds 6288 13th Circle S Fargo, ND 58104
	7/30/2010	8/17/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Todd Brown 6060 66th Ave. NW Berthold, ND 58718
Overburden was regraded	6/1/2010	6/12/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	John Erander PO Box 687 Stanley, ND 58784
Overburden was regraded	1960	10/21/2010	Hebron Brick Company 1000 Washington Ave. E Hebron, ND 58638	Wayne Petri 3265 County Road 90 Hebron, ND 58638
Overburden was regraded to approximate topography	1970		Hebron Brick Company 1000 Washington Ave. E Hebron, ND 58638	Wayne Petri 3265 County Road 90 Hebron, ND 58638
Overburden was regraded to approximate topography	1954		Hebron Brick Company 1000 Washington Ave. E Hebron, ND 58638	Hebron Brick Company 1000 Washington Ave. E Hebron, ND 58638
	4/1/1999		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
	7/16/2010	11/16/2010	Lyle's Construction 9660 Hwy 32 Wahalla, ND 58282	Stanley Metelmann 10150 Hwy 32 Wahalla, ND 58282
	4/18/2010		Susag Sand and Gravel, Inc. PO Box 23 Harvey, ND 58341	Donald Roerick 113 Main Ave. W Fargo, ND 58078
	6/4/2010	9/21/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Curtis Ones 10045 River Road Tolley, ND 58787

# SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2010  
 ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3813 (9/2001)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS							
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining	
Renville	30	160	85	Gravel	1.0	20,000		15'			
Rollette	5	160	70	Sand Gravel	9.6	28,700	30,900	5'	Cropland	Wildlife Habitat	
Stark	5	140	95	Gravel	9.0	56,000		15'	Rangeland	Pastureland	
Stutsman	27	139	62	Gravel	5.0	6,000	700	20'	Gravel Pit	Pastureland	
Towner	18	157	66	Gravel	0.5	20,000	800	35'	Gravel Pit		
Ward	1	154	84	Sand Gravel	7.8	57,000	18,900	18'	Rangeland	Pastureland Wildlife Habitat	
	3	153	81	Sand Gravel	2.2	36,200	7,200	10'	Gravel Pit	Pastureland	
	3	154	82	Sand Gravel	1.7	66,600	8,400	24'	Gravel Pit	Pastureland	
	9	154	86	Sand Gravel	1.2	45,800	2,900	24'	Gravel Pit Pastureland	Pastureland	
	12	156	85	Sand Gravel	4.0	94,500	15,700	15'	Pastureland	Pastureland	
	18	157	87	Gravel	1.0	10,000					

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (M/O/D/Y/R)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	4/21/2010	11/18/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Don Funke 302 Smith St. Tolley, ND 58787
	8/27/2010	10/6/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Dan Foss 8819 32nd Ave. Ralette, ND 58366
	11/15/2010	12/31/2010	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	George Sykora 3076 106th Ave. SW Dickinson, ND 58601
	5/1/2010	9/30/2010	Lindberg Brothers, Inc. PO Box 2115 Jamestown, ND 58402	Brolin Investing PO Box 2115 Jamestown, ND 58402
Overburden was regraded	5/1/1961		Miller Gravel & Ready Mix, Inc. PO Box 728 Cando, ND 58324	Roger Miller PO Box 728 Cando, ND 58324
	5/24/2010	7/10/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	American Rock & Sand Lessee 418 McKenzie Ave. Steele, ND 58482
	9/1/2010	9/18/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Dennis Anderson 12000 153rd St. SE Sawyer, ND 58781
	1/1/2010	12/31/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Sundre Sand & Gravel, Inc. 6220 37th Ave. SE Minot, ND 58701
	8/6/2010	8/18/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Durnell Properties 2000 104th St. SE Minot, ND 58701
	4/19/2010	6/16/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Donald Streitz 725 33rd Ave. SW # C Minot, ND 58701
	7/20/2010	8/31/2010	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Darrell Workman 21101 422nd St. NW Donnybrook, ND 58734

# SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2010  
 ND STATE SOIL CONSERVATION COMMITTEE  
 SFN 3814 (12/85)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Ward	18	152	84	Sand Gravel	15.0	98,215	5,893	Rangeland	Pastureland	
	26	156	85	Sand Gravel	2.3	44,500	11,100	Gravel Pit Pastureland	Pastureland	
Williams	5	155	100	Sand Gravel	2.1	59,400	8,500	Gravel Pit	Pastureland	
	5	155	100	Sand Gravel	5.7	175,800	23,100	Gravel Pit	Pastureland	
	5	155	96	Sand Gravel	7.1	80,300	11,500	Gravel Pit	Pastureland	
	23	155	101	Gravel		400		Hayland		
	30	150	10	Gravel	4.0	196,000	4,000	Hayland	Cropland	

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3814 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	4/1/2010	12/31/2010	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	John Navordvorsky Route 1 Box 86 Douglas, ND 58735
Overburden was regraded to appropriate original topography and topsoil was respread	8/20/2010	8/28/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Darrell Karma 2050 184th St. W Ryder, ND 58779
	10/14/2010	11/3/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Jerome Folvag 525 22nd St. E Williston, ND 58801
	7/6/2010	8/1/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Jerome Folvag 525 22nd St. E Williston, ND 58801
Overburden was regraded to appropriate original topography and topsoil was respread	9/20/2010	10/9/2010	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Robert Sheldon 10971 60th St. NW Tioga, ND 58852
	1999		Kulland Excavating & Gravel, Inc. 1505 58th St. W Williston, ND 58801	Kenneth Heen 410 17th St. W Williston, ND 58801
Overburden was regraded	5/1/2010	6/20/2010	Northern Improvement Co. PO Box 1035 Dickinson, ND 58601	Northern Improvement Co. PO Box 1035 Dickinson, ND 58601