


2011 SURFACE MINING REPORT



For Minerals Other Than Coal

PREPARED BY: ND STATE SOIL CONSERVATION COMMITTEE - BISMARCK, ND

**SUMMARY
OF
SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL**

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 2011.

There were 20 surface mining operators reporting for the calendar year 2011. The following are approximate total operations according to the reports submitted:

1.	Acres affected	551.6	
2.	Minerals mined		
	A) Gravel & Sand	5,932,365	cubic yards
	B) Clay	71,563	cubic yards
	C) Scoria	381,715	cubic yards
	D) Rock	555	cubic yards
	TOTAL	6,386,198	cubic yards
3.	Overburden disturbed	1,237,723	cubic yards

There are 64 pits ranging in size from .25 to 30 acres. Minerals mined were gravel, sand, clay, scoria and rock.

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2011
 ND STATE SOIL CONSERVATION COMMITTEE
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS						
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
Bottineau	28	162	82	Gravel	7.1	29,500	11,450	6'	Gravel Pit	Wildlife Habitat
Bowman	11	129	102	Gravel	7.0	26,000		6'	Hayland	Pastureland Cropland
Burke	15	160	91	Gravel	9.6	27,500	45,500	10'	Gravel Pit	Pastureland
	26	160	92	Gravel	2.0	18,500	4,000	7'	Hayland	
	26	161	92	Gravel	5.0	40,000	1,000	10'	Hayland Gravel Pit	
	35	160	91	Gravel	1.0	6,000		10'	Hayland	Pastureland
Burleigh	27	140	77	Gravel	6.2	50,000	6,000	6'	Cropland	Cropland
	28	140	77	Sand Gravel	14.0	180,000	18,000	8'	Hayland	Pastureland Cropland
	28	140	77	Gravel	6.0	75,000	3,000	8'	Rangeland	Pastureland
Divide	2	160	96	Gravel	5.0	147,420	17,562	20'	Gravel Pit	Industrial
Grand Forks	8	149	52	Sand Gravel		8,263	200	8'		

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	10/17/2011	11/7/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Carol Moe 2206 Lynwood Drive Champaign, Ill 61821
Overburden was regraded and topsoil was respread	11/14/2011	12/9/2011	Melvin Miller Construction, Inc. Hwy 12 W Bowman, ND 58623	John Johnson 11462 Ladner Road Buffalo, SD 57720
Overburden was regraded and topsoil was respread	8/22/2011	9/15/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Les Martner 8049 County Road 16 Kenmare, ND 58746
Overburden was regraded and topsoil was respread	10/3/2011	10/25/2011	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Tom Lucy 8575 85th Ave. NW Powers Lake, ND 58773
	7/14/2011	7/31/2011	Sandberg Redi-Mix, Inc. PO Box 84 Lignite, ND 58752	Murfel Smith 8447 91st St. NW Powers Lake, ND 58773
Ready for Seeding	4/5/2011	5/23/2011	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Robert Neuenfeld Box 516 Kenmare, ND 58746
Overburden was regraded and topsoil was respread	5/1/2011	7/1/2011	Knife River Corporation 2370 Vermont Ave. Bismarck, ND 58504	Monte Dralle 10000 275th St. NE Sterling, ND 58572
Overburden was regraded and topsoil was respread	5/7/2001		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
Overburden was regraded and topsoil was respread	5/13/2002		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
	8/17/2011	9/9/2011	Knife River Corporation 4787 Shadow Wood Drive NE Sauk Rapids, MN 56379	Richard Skor 8 Hamlet Ave. Wildrose, ND 58795
			Harley & Judy Camperud 2732 6th Ave. Northwood, ND 58267	Grensrich Farms Rural Route Northwood, ND 58267

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2011
 ND STATE SOIL CONSERVATION COMMITTEE
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Grand Forks	12	149	52	Rock		555		6'	Pastureland	
Kiddier	11	142	74	Gravel	18.5	350,000	90,000	25'	Pastureland	
	11	142	74	Gravel	22.0	589,250	70,196	20'	Pastureland	
	13	140	73	Sand Gravel	1.8	33,818	2,819	12'	Hayland	
	23	139	74	Sand Gravel	1.9	37,398	3,109	12'	Hayland	
Logan	13	133	73	Gravel	12.4	40,000	8,000	10'	Cropland	
	30	136	72	Sand Gravel	3.4	42,019	5,364	8'	Hayland	
Mchenry	13	153	80	Gravel	18.6	56,700	2,000	15'	Pastureland	
Mckenzie	23	149	98	Scoria	2.0	78,157	5,500	16'	Gravel Pit Rangeland	
	32	151	97	Scoria	30.0	154,238	150,000	18'	Gravel Pit Rangeland	
McLean	12	146	82	Gravel	8.0	62,220	36,000	20'	Pastureland	

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
			Harley & Judy Camperud 2732 6th Ave. Northwood, ND 58267	Robert Lentz 1951 5th Ave. Thompson, ND 58278
Overburden was regraded and topsoil was respread	4/1/2011	12/1/2011	Knife River Corporation 2370 Vermont Ave. Bismarck, ND 58504	Dean Wong 6131 Goodview Trail N Hugo, MN 55038
	8/15/2011	9/30/2011	Knife River Corporation 4787 Shadow Wood Drive NE Sauk Rapids, MN 56379	Dean Wong 6131 Goodview Trail N Hugo, MN 55038
Topsoil was respread	8/9/2011	9/14/2011	Hoffer Sand & Gravel 5353 40th Ave. SE Tappen, ND 58487	Scott Underwood 528 West 8th St. S Brookings, SD 57006
Topsoil was respread	6/8/2011	6/30/2011	Hoffer Sand & Gravel 5353 40th Ave. SE Tappen, ND 58487	Richard Mortlock 3829 24th Ave. SE Steele, ND 58482
Overburden was regraded and topsoil was respread	7/1/2011	8/1/2011	Knife River Corporation 2370 Vermont Ave. Bismarck, ND 58504	John Bitz 6362 Hwy 3 Napoleon, ND 58561
Overburden was regraded and topsoil was respread	10/6/2011	11/5/2011	Hoffer Sand & Gravel 5353 40th Ave. SE Tappen, ND 58487	Bill Hoffer 5353 40th Ave. SE Tappen, ND 58487
	10/7/2011	11/30/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Curtis Flest Box 42 Velva, ND 58790
Overburden was regraded and topsoil was respread	4/15/2011		Three Way, Inc. PO Box 250 Buffalo, WY 82834	Randy Stevenson 2131 122nd Ave. NW Walford City, ND 58854
Overburden was regraded and topsoil was respread	1/16/2011		Three Way, Inc. PO Box 250 Buffalo, WY 82834	Ivan & Florence Johnson Trust PO Box 1446 Williston, ND 588023
	9/22/2011	10/15/2011	Falkirk Mine 2801 1st St SW Underwood, ND 58576	Falkirk Mine 2801 1st St SW Underwood, ND 58576

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2011
 NID STATE SOIL CONSERVATION COMMITTEE
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
McLean	15	153	91	Gravel	8.9	26,000	14,300	12'	Feedlot	Feedlot
	22	150	80	Sand Gravel	6.3	151,500	25,200	15'	Pastureland	Pastureland
	30	144	80	Gravel	4.0	100,000	8,000	10'	Hayland	Cropland
	3	144	88	Scoria	1.7	44,809	2,750	15'	Rangeland	Pastureland
Mercer	4	144	88	Scoria	2.0	64,511	20,000	40'	Rangeland	Pastureland
	21	146	87	Gravel	2.0	2,704	9,700	15'	Rangeland	Pastureland
	34	146	87	Gravel	2.5	23,547	12,100	10'	Rangeland	Pastureland
Morton	4	140	90	Clay	1.0	32,000	60,000	70'	Rangeland	
	11	140	90	Clay	1.0	39,243	3,000	20'	Rangeland	
Mounttrail	10	157	90	Gravel	3.0	16,000	4,000	6'	Rangeland	
	17	157	94	Sand Gravel	14.0	367,814	43,817	20'	Hayland	Industrial

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to appropriate original topography and topsoil was respread	7/1/2011	8/21/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Lynn Billadeau 69th Ave. SW Parshall, ND 58770
Overburden was regraded to appropriate original topography and topsoil was respread	5/20/2011	7/9/2011	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Randy Heiser 2536 14th Ave. NW Ruso, ND 58778
	8/15/2008		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Shirley Jennings 3802 Normandy St. Bismarck, ND 58503
	11/1/2011	12/31/2011	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	8/30/2011	9/14/2011	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	8/4/2011	8/24/2011	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	8/8/2011	9/30/2011	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
Overburden was regraded	1970		Hebron Brick Company 1000 Washington Ave. E Hebron, ND 58638	Wayne Petri 3265 County Road 90 Hebron, ND 58638
Overburden was regraded	1954		Hebron Brick Company 1000 Washington Ave. E Hebron, ND 58638	Hebron Brick Company 1000 Washington Ave. E Hebron, ND 58638
	11/21/2011	1/9/2011	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Neil Bivier 7605 81st Ave. NW Stanley, ND 58784
	9/13/2011	12/8/2011	Knife River Corporation 4787 Shadow Wood Drive NE Sauk Rapids, MN 56379	Glen & Joanne Enger 10094 70th St. NW Tioga, ND 58852

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2011
ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Mountrail	19	156	88	Gravel	13.2	53,500	31,900	15'	Gravel Pit	Pastureland
	20	153	89	Gravel	8.6	19,700	6,950	15'	Cropland Rangeland	Pastureland Cropland
	23	155	91	Gravel	28.0	39,000	14,000	8'	Cropland	Cropland
	24	156	89	Gravel	23.0	235,000	35,250	12'	Rangeland	Pastureland
	26	156	94	Gravel	41.5	316,833	14,150	35'	Rangeland	Pastureland Wildlife Habitat Industrial
	27	153	91	Gravel	17.2	126,000	24,000	12'	Cropland	Cropland
	28	157	93	Gravel	16.5	67,000	39,930	8'	Gravel Pit Rangeland	Pastureland
	29	152	92	Gravel	22.8	79,800	73,568	10'	Cropland	Cropland
	32	153	91	Sand Gravel	4.6	110,000	13,000	15'	Cropland	Cropland
Pembina	5	162	56	Gravel	0.8	14,726	300	15'	Cropland	
Pierce	30	152	72	Gravel	3.0	21,000	300	18'	Cropland	Cropland

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	10/25/2011	12/1/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Robert Wirtz 6280 66th Ave. NW Blaisdell, ND 58718
	8/25/2011	10/25/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	John Bartelson 4340 71st Ave. NW Parshall, ND 58770
Overburden was regraded and topsoil was respread	9/22/2011	11/5/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Warren Craft 8020 56th St. NW Stanley, ND 58784
	4/10/2011	12/15/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Dallas Moore 6290 67th Ave. NW Blaisdell, ND 58718
	1/1/2011	10/15/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Dale Lalim Box 638 Toga, ND 58852
Overburden was regraded and topsoil was respread	6/30/2011	10/26/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Jack L. Fladeland 4223 Hwy 8 New Town, ND 58763
Overburden was regraded and topsoil was respread	11/8/2011	12/23/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Doug Feiring 6698 94th Ave. NW Powers Lake, ND 58773
	4/25/2011	10/25/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Kenneth H. Reynolds 6288 13th Circle S Fargo, ND 58104
	9/23/2011	10/22/2011	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Brooks Annala PO Box 2765 Gillette, WY 82717
	6/14/2011	10/25/2011	Lyle's Construction 9660 Hwy 32 Wahalla, ND 58282	Stanley Metelmann 10150 Hwy 32 Wahalla, ND 58282
Topsoil was respread	4/30/2011		Susag Sand and Gravel, Inc. PO Box 23 Harvey, ND 58341	Donald Roerick 113 Main Ave. W Fargo, ND 58078

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2011
 ND STATE SOIL CONSERVATION COMMITTEE
 SFN 3813 (10/2003)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS				Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Ramsey	2	152	62	Clay Sand Gravel	3.0	320 795 44,562		13'	Cropland Gravel Pit	Pastureland
Renville	4	159	85	Gravel	0.3	10,000		20'	Gravel Pit	Pastureland
	7	162	86	Gravel	1.0	35,000		12'	Rangeland	
	30	160	85	Gravel	1.0	160,000		15'	Gravel Pit	
	30	160	85	Gravel	3.0	23,500	1,500	25'	Gravel Pit	Industrial
Stutsman	10	139	62	Gravel	21.0	28,700	6,500	15'	Hayland	Pastureland
	14	138	68	Gravel	2.0	30,000	5,000	15'	Cropland	Cropland
Towner	18	157	66	Gravel	2.0	22,560	1,000	35'	Gravel Pit	
Walsh	33	156	56	Sand Gravel	3.9	62,500	9,300	10'	Gravel Pit	Pastureland
Ward	3	154	82	Sand Gravel	1.9	72,000	6,000	24'	Gravel Pit	Pastureland
	18	152	84	Gravel	7.0	95,000	2,000	20'	Gravel Pit	Industrial

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	5/23/2011	12/7/2011	Soper Construction, LLP 513 Goulding Road Devils Lake, ND 58301	Carla Christofferson 1940 Outpost Circle Los Angeles, CA 90068
	8/18/2011	8/23/2011	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Renville County 205 Main St E Mohall, ND 58761
	9/6/2011	11/20/2011	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Curtis Ones 10045 River Road Tolley, ND 58787
	5/24/2011	10/31/2011	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Don Funke 302 Smith St. Tolley, ND 58787
	9/16/2011	10/16/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Don Funke 302 Smith St. Tolley, ND 58787
	9/19/2011		Aggregate Industries 800 Holiday Drive #240 Moorhead, MN 56561	Kevin & Jean Syverson 2610 12th St. S Fargo, ND 58103
Overburden was regraded to approximate topography	8/1/2011	11/1/2011	Knife River Corporation 2370 Vermont Ave. Bismarck, ND 58504	Shari Schlect 4498 58th Ave. SE Gackle, ND 58442
Overburden was regraded	1961		Miller Gravel & Ready Mix, Inc. PO Box 728 Cando, ND 58324	Roger Miller PO Box 728 Cando, ND 58324
	8/24/2011	9/9/2011	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Robert Miller 6010 Hwy 32 Fardville, ND 58231
	1/1/2011	12/31/2011	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Sundre Sand & Gravel, Inc. 6220 37th Ave. SE Minot, ND 58701
	5/27/2011	6/22/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	John Navordvorsky, Jr. 2301 114th St. SW Douglas, ND 58735

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2011
 ND STATE SOIL CONSERVATION COMMITTEE
 SFN 3813 (9/2001)

LOCATION OF MINING OPERATION				CURRENT YEAR OPERATIONS						
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
Williams	2	153	102	Sand Gravel	5.5	176,700	53,000	20'	Pastureland	Pastureland
	2	154	96	Scotia	5.0	40,000	10,000	30'	Rangeland	
	5	155	100	Sand Gravel	9.6	306,500	38,520	20'	Gravel Pit	Pastureland
	5	159	95	Sand Gravel	5.5	71,000	10,700	8'	Hayland	Hayland
	6	156	99	Gravel	9.7	47,530	31,300	15'	Rangeland	Pastureland
	17	159	98	Gravel	9.6	28,000	7,000	10'	CRP	Wildlife Habitat
	20	155	100	Sand Gravel	30.0	841,606	100,258	20'	Hayland	Industrial
	30	150	100	Gravel	4.0	230,000	4,000	15'	Hayland	Cropland
	30	155	100	Gravel	19.5	56,700	15,730	20'	Hayland	Pastureland

ND STATE SOIL CONSERVATION COMMITTEE
 SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAYR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/Completed		
	10/17/2011	12/3/2011	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	MMW&W, LLC 135 Rickman Industrial Drive, Ste. 100 Canton, GA 30115
	4/6/2011	9/5/2011	Harris Graveling, Inc. PO Box 367 Kenmare, ND 58746	Kelly Gleave 10683 Hwy 1804 Toga, ND 58852
	4/6/2011	8/11/2011	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Jerome Folvag 525 22nd St. E Williston, ND 58801
	11/23/2011	12/11/2011	Sundre Sand & Gravel 4103 55th St. SE Minot, ND 58701	Gregory Quame 117 23rd St. E Williston, ND 58801
	6/23/2011	7/18/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Travis Twitchell 12877 67th St. NW Williston, ND 58801
Overburden was regraded to appropriate original topography and topsoil was respread	4/15/2011	5/25/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Cathy Holgerson 802 15th Ave. W Williston, ND 58801
	7/5/2011	12/8/2011	Knife River Corporation 4787 Shadow Wood Drive NE Sauk Rapids, MN 56379	Knife River Western North Dakota 5654 134th Ave. N Williston, ND 58802
Overburden was regraded	8/15/2011	11/15/2011	Northern Improvement Co. PO Box 1035 Dickinson, ND 58601	Northern Improvement Co. PO Box 1035 Dickinson, ND 58601
	11/21/2011	12/10/2011	Aggregate Construction, Inc. PO Box 239 Minot, ND 58702	Sandi Qualley/Hilda Treffry Trust 9723 Aspen Hollow Way Fairfax, VA 22032